ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 14 | Bagalakunte |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0110, W0057, W0055, W0142, W0053, W0051, W0104, W | NA, Om Shakthi Lyt 8th Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, 4th Cro | Bagalagunte |
| **Segment No.** | **Total Length (m)** | |
| 14/C-W0110/S060252 | 984.70 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 122.14 | 77.493757 | 13.053404 | 77.493062 | 13.053919 | 1st Main | Deadend |
| 2 | 156.69 | 77.493842 | 13.053717 | 77.492454 | 13.054086 | 1st Main | Deadend |
| 3 | 154.25 | 77.495834 | 13.068024 | 77.495620 | 13.066646 | 2nd main | Deadend |
| 4 | 240.92 | 77.496154 | 13.067972 | 77.495759 | 13.065829 | PaiGarden | Siddeshwra temple |
| 5 | 104.55 | 77.496442 | 13.067926 | 77.496277 | 13.066994 | PaiGarden | Deadend |
| 6 | 206.15 | 77.495091 | 13.067577 | 77.496485 | 13.066984 | PaiGarden | Deadendl |

## Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to U G D works and Sinking of Boreweiiin ward no 14 T Dasrahalli subdivision | 10000000 | 2019-20 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2019 - 2020 | Others | Sinking Boreweii |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | | 014-19-000046 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE/DD/WO/430/2020-21 | 27/11/2020 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 27/11/2020 | 26/11/2021 | No |

## Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| Sri R Shivaram | | 6700000.00 |

**Zone:** DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0110, W0057, W0055, W0142,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Scanned by CamScanner

| Phone No. | E-Mail ID | Name |
|---|---|---|
| 9036033962 | | Chetan KM |

## Field Inspection Details

| Number of Trees | Any Other Information |
|---|---|
| 30 | Pipeline works |
| **Date of Inspection** | **Remarks** |
| 07/01/2021 | Borewell works |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Footpath Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|

**Zone:** DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0110, W0057, W0055, W0142,

ಸಹಾಯಕ ಕಂದಾಯ ಅಧಿಕಾರಿಯವರು
ಡಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Scanned by CamScanner